

Focusrite
Producer Pack

Meter 0 Vu Calibration Listen Input

+4dBu +18dBu Audio O/L

Meter Source

INST INPUT

20-50 30-60 Mic +48V

Gain Select Mic Impedance ISA 110 Med High

Line Inst

Phase +25 +10 +20 +40

Trim Inst

Insert 1 In EQ Split

All EQ

Filter In 800 5k 22k

400 200 1k6

300 1k6

Comp Gate

Param EQ In

Shelving EQ In

Comp Gate

600 200 400 1200

110 40 120

x3

1.5 0.6 1.8

3 9 18

Comp Gate

270 655 160 460

95 56 33 20

4.7 3.3 6.8 15 10 18

2.2 1.5 kHz

HI Range

Meter 0 Vu Calibration Listen Input

+4dBu +18dBu Audio O/L

Meter Source

Post Dyn Dyn Split

Dynamics

Pre EQ Post Sum

Vintage

Comp 3 Lim

1.5 Ratio

Ext Key

Comp In

Makeup

Insert 2 In Post Dyn Dyn Split

Dynamics

Pre EQ Post Sum

Vintage

Comp 3 Lim

1.5 Ratio

Ext Key

Comp In

Makeup

Gate In Expand Listen Ext Key Fast Att Hyst

-30 -20 -15 -10 -5

0 80 20ms 4s 0.1

0 10 20

0 80 20ms 4s 0.1

0 80 20ms 4s 0.1

0 80 20ms 4s 0.1

0 80 20ms 4s 0.1

De-Ess In

Active

3k2 7k2

Frequency

De-Ess Listen

Threshold

-20 +10

Ext Sum

Bypass

De-Ess In

Active

3k2 7k2

Frequency

De-Ess Listen

Threshold

-20 +10

Ext Level Mute

0 -60

0dB

Ext Level Mute

0 -60

0dB

Ext Sync

Soft Limiter

1 2

ADC Level dBFS

Output Input

0 -2 -4 -6 -8 -10 -12

192 176.4 96 88.2 48 44.1

24 20 16

Bit Depth Select

Clock Select

Lock Word Clock 256X

ADC Inputs

POWER

